A record of the detail.

Historic QA sample | March 2021

An excerpt from Firetree's supplied QA Example report.
The following page shows the original action-required record
and a later installed record, with photographic evidence.

Example record fields:
Pin / location reference, date, installer, status, FRR, substrate,
service type, orientation, installation system and comments.

This is an example of record structure and traceability.
It is not a current installation instruction or a project certificate.

Project address details have been removed for this website sample.

Company: Firetree Installations
Location: Website sample - project details removed

0003:01 - History 1 of 2 (earliest)



Pin Photos
1 of 1

Pin Number: 0003:01
Date Added: 03/03/2021 - 10:33

Status: Action required
Rating: FR
FR: -/60/60
Substrate: Traydeck
Item Type: 40mm PVC Pipe
Orientation: Floor
Length: -
Comments:
Install Collar

0003:01 - History 2 of 2 (latest)



Pin Photos
1 of 1

Pin Number: 0003:01
Date Added: 08/03/2021 - 11:39

Status: Installed
Rating: FR
FR: -/60/60
Substrate: Traydeck
Installation Type: Ryanfire Drop In Collar + Mastic + Concrete Screws
Item Type: 40mm PVC Pipe
Orientation: Floor
Length: -
Comments:
Install Collar